



view from St. Vincent Street, with existing chimney conditions, TV aerials and street power pole

exist. GFL 5.65 (0000) exist. GL 5.43 (-0220)



existing verandah tiles with excessive grout and cracked front facade (tiles likely been relayed poorly)



existing front facade with two-tone paint, cracks in render, exposed conduits and street light pole



existing rusted iron roof sheeting with chimney features removed

chimney of no.97 St. Vincent Place. refurbish chimneys to match with mouldings and pots. 11745 exist. ridge 15.50 (9850) existing boundary walls retained 2695 7085 demolish by hand roof structure behind brickwall. prop wall to Structural Engineers details. exist. FCL 12.96 (7310) 12.80 (7150) stair FL 12.29 (6640) exist. wall 11.40 (5750) exist. FFL 9.59 (3940) exist. GCL 9.27 (3620) exist. FFL 8.76 (3110) exist. wall 8.45 (2580) exist. land. 7.93 (2280) exist. wall 7.75 (1880)


demo. elevations


exist. GFL 5.65 (0000) exist. GL 5.33 (-0320)


studio 35 architect






















1 Investigate existing paint finishes on existing form. Remove paint and reinstate original render. Make good



New powder coated aluminium window frames in Dulux 'Monument' with enviro double glazing





Reinstate slate tiles with Glendyne slate roof tiles. COS colour to match neighbouring no.97



Aluminium louvered screening - Colorbond





3 Existing timber painted Peter 4 Existing cast iron elements, Lewis Paints 'Linseed-oil window frames & front doo window frames & front door in Dulux Super Enamel semi-gloss 'Monument - C29'



9a James Hardie 'Easylap' fibre cement sheet cladding and Lysaght klip-lok steel roofing and fascia in Colorbond 'Monument'





5 AHBP '011 (LB) S' Blended Bricks 400mm I 1 12

Bricks 400mm L x 40mm H

New gutters and downpipes in *Colorbond* 'Surfmist'



6 Natural Limestone cladding 20mm thick


Basalt plinth and wall base





Design Principle:

Two tone colour scheme proposed to walls, fenestration, and detailing similar to 75 St. Vincent Place South, Albert Park









- Investigate existing paint finishes or existing form. Remove paint and reinstate original render. Make good
- Reinstate slate tiles with Glendyne slate roof tiles. COS colour to match neighbouring no.97
- Existing fascias, window architrave and front door frame painted Peter Lewis Paints 'Linseed-oil paint -Black Oxide'
- Existing gutters, fence, fenestration cast iron elements, windows & front door in Dulux - Super Enamel semi-gloss 'Monument - C29'
- AHBP '011 (LB) S' Blended Bricks 400mm L x 40mm H x 90mm D
- Natural Limestone cladding 20mm thick
- New powder coated aluminium window frames in Colorbond 'Monument' with grey non-reflective enviro double glazing
- Aluminium louvered screening Colorbond 'Monument'
- Fibre cement sheet cladding in Dulux 'Natural White Half'
- Fibre cement sheet cladding and fascia in Dulux 'Monument -C29' to match slate roof COS
- Lysaght klip-lok steel roofing and fascia in Colorbond 'Monument'
- New gutters and downpipes in Colorbond 'Surfmist'
- 12 Basalt plinth and wall base, saw cut



