

History, Significance & Condition

Kardinia House VHR H0337 1 Riverview Terrace, Belmont 3216

AuthorTrethowan ArchitectureDate24 March 2025

ARCHITECTURE INTERIORS HERITAGE Trethowan Architecture acknowledges the Traditional Owners of the lands on which our studio and projects are located. We pay respects to Elders past, present and emerging.

CONTENTS

1	Histo	History					
	1.1	Summary	1				
	1.2	Detail History	2				
2	Physi	ical Analysis	14				
	2.1	Introduction	14				
	2.2	Site Context	14				
	2.3	Site Plan	14				
	2.4	The House	14				
	2.5	Interiors	14				
	2.6	Outbuildings	14				
	2.7	Additions	14				
	2.8	Other buildings	15				
3	Site S	Survey Data Sheets	16				
4	Signi	ficance	44				
	4.1	Victoria Heritage Register	44				
	4.2	Permit exemptions	45				
	4.3	Greater Geelong Planning Scheme	47				
	4.4	Levels of Significance	48				
	4.5	Significance Plan	49				
5	BIBL	IOGRAPHY	50				
	5.1	BOOKS /REPORTS	50				
	ARCH	IVAL RECORDS AND HERITAGE COLLECTION	50				
	5.2	NEWSPAPERS AND JOURNALS	50				

ARCHITECTURE INTERIORS HERITAGE

1 History

The Traditional Owners of the land for the area are the Wadawurrung People.

1.1 Summary

In 1837, Dr. Alexander Thomson from Scotland took up land on the Barwon River. Thomson was a medical officer and was considered one of the founders of Geelong, which was gazetted as a town in 1838. Initially, a timber hut was constructed on site, which was then replaced by a single-storey stone house between 1850 and 1855.

Thomson constructed Kardinia House in various stages. The original timber structure was replaced by a stone house between 1850 and 1855. Thomson was a highly influential man, both in Geelong and across Victoria. In 1843 he was one of the Port Phillip members to the New South Wales Legislative Council. In 1844 he resigned, protesting the need to travel to Sydney to attend Parliament. He became an active campaigner for the separation movement, which ultimately saw Victoria become an independent colony from New South Wales. In 1851 Thomson became Geelong's first mayor. He was elected to the Victorian Legislative Council from 1852-54 and helped draft the Victorian Constitution bill. He then returned as Geelong's mayor in 1855-57 and served in the Victorian Legislative Assembly in 1857-59. His career also saw him become director of the Geelong-Melbourne Railway Co, and he was active in starting and promoting Presbyterian services in the Geelong region. Thomson died in 1866. Subsequent owners of Kardinia included John Richardson, Member of the Legislative Assembly, William Sommers, a mayor of Geelong, and Horace Frank Richardson, councillor and Member of the Legislative Council. Though the fabric of the stone house from 1850-55 is still visible on the site, it has been transformed and extended extensively. In 1869 further additions were made to Kardinia House, including a second storey. In the 1880s bay windows and a verandah were added. From 1947-1986 Kardinia House was used as a children's home for the Salvation Army, catering mainly for toddlers aged two to five years' old. This led to extensive changes to the building's interior and the grounds. From 1965 cottage homes were opened on the property, allowing siblings to remain together. More recently, Kardinia House was used as the headquarters of a non-profit organisation providing disability, senior and employment services.

1.2 Detail History

The following history was researched by Dr David Rowe and is reproduced with permission.

The original dwelling of 1837 appears to have been a rudimentary hut as shown in the following image:




Image of Thomson's hut, "Kardinia" in 1840. Source: Wynd collection, Authentic Heritage Services Pty Ltd.

Thomson's dwelling was described by the Rev. Dr Lang in 1847 (from a visit in early 1846):

KARDINIA, Dr. Thomson's residence is situated on the summit of the natural terrace to which I have already alluded, on the right bank of the Barwon, the garden occupying the steeply declivity in front. It was one of the earliest habitations ... and as it was necessarily erected on Government land, on which, of course, it was not expedient to go much expense, to tempt the cupidity of some rival competitor at the next Crown land sale, it was constructed of slight materials, and was not intended to have the character of permanence.[1]

It was in April 1846 when Thomson applied for the freehold of this site. This is outlined in a 'Sketch shewing the Suburban Allotments in the Parish of Barrarbool (applied for by A. Thomson' reserving a road of 99 feet wide along the bank of River':

ii




R. Hoddle, Extract of 'Sketch shewing the Suburban Allotments in the Parish of Barrarbool (applied for by A. Thomson), 21 April 1846. Source: VPRS 8168/P002, SYDNEY B8, Barrarbool, Public Record Office Victoria.



R. Hoddle, 'Sketch shewing the Suburban Allotments in the Parish of Barrarbool (applied for by A. Thomson), 21 April 1846. Source: VPRS 8168/P002, SYDNEY B8, Barrarbool, Public Record Office Victoria.

Thomson had relocated to Malop Street in 1844 to continue his medical practice. [2] He returned to "Kardinia" in 1845.[3] His purchase of the freehold in 1846 might have given him confidence to construct a more permanent dwelling about this time. In 1850 in the Geelong Council Rate Books (entry 364), "Kardinia" was described as being of wood comprising five rooms, with a lodge and garden. It had a net annual value of £55.[4] By 1852, the dwelling had been extended to 9 rooms with a net annual value of £95.[5] It was also in 1852 when Thomson offered the lease of "Kardinia" 'for a term of years', the dwelling and out-offices being described as 'extensive' and 'commodious, and replete with every convenience, suitable for a family of the first respectability. [6]

The original (c.1846-50) portion of "Kardinia" appears to have comprised a central, hipped roofed wing with front verandah (with timber detailing). This is revealed in the earliest-known photograph of the property which was likely taken in 1866 by John Norton. Several other photographs of similar style taken by John Norton in Geelong are dated 1866 (see State Library of Victoria images). The photograph forms part of a broader image of William Gray's flour mill on the north bank of the Barwon River, with "Kardinia" in the background. The flour mill was altered and extended into the Albion Woollen Mill in 1869 for Alexander Gray. [7] and these major additions are not shown in the Norton photograph, giving further weight that the photograph is dated to 1866 (the additions to the mill are shown in one of the Webb paintings – see later discussion).



"Kardinia House", c.1866 (extract of a larger photograph - see following). Source: GRS 2009/02172, Geelong Heritage Centre Collection.

iν



Gray's Mill, Geelong, n.d. [c1866] with "Kardinia House" in the background on the left.


Source: GRS 2009/02172, Geelong Heritage Centre Collection.

The photograph shows that the c.1846-50 hipped roofed "Kardinia" dwelling was flanked by stone attic gabled wings by 1866. These wings included faceted bay windows on the ground floor, attic windows, and decorative bargeboards and finials. The provenance of these wings is alluded to (but is not entirely clear) in the Geelong Council Rate Books. In 1853, "Kardinia" was listed as being of weatherboard comprising 12 rooms with a net annual value of £250.[8] The following year, 1854, when leased to a Mr Herring, it comprised 7 rooms, kitchen and garden with a net annual value of £400[9] (possibly reflecting the high property values as a consequence of the gold rush). All rate book entries to 1857 describe the dwelling as being constructed of weatherboard, and not stone as shown in the historic photograph of c.1866. However, it is clear that the original and early fabric during Thomson's ownership of "Kardinia" is that shown in Norton's photograph.

Following Thomson's death in 1866, the property passed to his wife, Barbara Thomson. After her death in 1867, the son in law of Alexander Thomson, Henry Creswick, took up ownership, possibly on behalf of this wife, Jane Creswick (nee Thomson)[10]. The property was leased until 1876 to John Richardson, Town Clerk, South Barwon.[11] During Richardson's occupation in the 1870s, glimpses of "Kardinia" were revealed in paintings of the Barwon River by Alexander Webb. Both paintings appear to reflect the dwelling as it was shown in 1866. This suggests any two storey addition as outlined in the Statement of Recommendation, could not have occurred in 1869, or at least to a front portion of the dwelling.



A. Webb, "Kardinia and flour mill", n.d [c.1870s]. Note "Kardinia House" on the left. Source: Geelong Gallery in V. Filmer, Alexander Webb 1813-1892, Geelong Art Gallery Inc., 1990.



A. Webb, "Barwon River from the bridge", n.d [c.1870s]. Note "Kardinia House" and its early setting on the left. Source: Geelong Gallery in V. Filmer, Alexander Webb 1813-1892, Geelong Art Gallery Inc., 1990

vi



Detail of Webb's painting, "Barwon River from the bridge", showing Thomson's "Kardinia House" and front (northern setting). The depiction of the dwelling reflects Norton's photograph of c.1866.

The existing dwelling would appear to reflect substantial alterations and additions that were made during the ownership of the local publican, William Sommers. He owned the property from 1881 until 1890.[12] As outlined in the South Barwon Rate Books, the net annual value of the property increased from £80 in 1882 to £95 in 1883-84 and £100 in 1886-87.[13] This gives weight to the existing appearance of the two storey painted portion of "Kardinia" largely being associated with significant alterations and additions for William Sommers. Further physical analysis is required to confirm the extent of the changes, but they appear to have included:

- Two storey additions to the early flanking gabled wings (or completely new two storey wings).
- Two storey addition to the central wing linking the flanking gabled wings.
- Cast iron balcony and verandah.

Aerial photographs by Charles Pratt in the 1920s reveal that gabled balconies had also been constructed above the ground floor bay windows. Physical evidence of the gable roof to the west balcony is in the lines on the walls and adjacent to the first floor windows.



Aerial view showing western portion of "Kardinia" with gable roofed balcony above the western bay window, c.1925. Source: C. Pratt, accession H91.160/590 State Library of Victoria.

The design detail of the cast iron valances and brackets to the verandah and balcony at "Kardinia", particularly the timber framed cast iron valances with Rinceau patterning (a sinuous and branching scroll of thistle-like steams and leaves, and rose flowers) are known to have been widely employed in the work of the prolific local architects, Joseph Watts and John Stuart Jackson in the 1880s (both separately, and in partnership between 1881 and 1883).[14] The cast iron valances seen at "Kardinia" were also adopted (in part) with their design of Price Villa, Eastern Beach Road (now facing Fitzroy Street) in 1883[15] as shown in the following historical photograph.






Price Villa (when facing Eastern Beach Road), n.d. The verandah and balcony valances (but without the drops) are identical to "Kardinia House". Source: Noel Rudolph.

Detail of north wing of the Austin Hall showing cast iron detailing, 2007. Source: David Rowe.

The same valance construction and pattern as "Kardinia" is also identified in other Watts-designed buildings including Austin Cottages and Hall, South Geelong (1886-98) and Wellwood Terrace, Gheringhap Street (1887).[16] Of the latter, the first floor balustrade pattern is also identical to that at "Kardinia". At the former St. Mary's Presbytery (designed by Joseph Watts in 1886[17]), the valance and first floor bracket patterns reflect those at "Kardinia" (the valances to both floors and the first floor brackets).

viii





St. Mary's Presbytery, Yarra Street, 2016. Source: David Rowe.

Cast iron pattern, first floor balcony, Wellwood Terrace, 1991. Source: David Rowe.

No tender notices have been identified in the *Geelong Advertiser* linking Joseph Watts and/or John Stuart Jackson to the alterations and additions of "Kardinia". The involvement of one or both of the architects is possible given their associations with William Sommers (in addition to the use of well-known cast iron patterns by the architects). In 1882, Watts and Jackson won the competitive design for the Exhibition Hall Theatre, Geelong.[18] Sommers was a Director of the Exhibition Hall Company.[19] Between 1881 and 1885, Jackson also held the lease of the Exhibition Hall.[20] In 1889, Watts designed additions to Sommers' Victoria Hotel, Geelong.[21] The close relationship between Jackson and Sommers was revealed in the *Geelong Advertiser* in 1884 when it was reported that Sommers was a groomsman at Jackson's wedding at St. Paul's Church, Geelong.[22]

Architecturally, the steeply-pitched gabled roof forms, decorative bargeboards and incised quatrefoil motifs in the gable ends at "Kardinia" share a passing resemblance with the gate lodge at the Geelong Eastern Cemetery, design by Joseph Watts in 1888-89.[23]

Historical and physical evidence also reveals other elements of the 1880s design now altered or missing. This includes (but is not limited to) the gabled balcony roofs with cast iron decoration above the bay windows and the faceted ground floor bay window in the in the central wing behind the verandah. These details are shown in photographs of the early twentieth century.

It was in 1890 when the property was taken over by Horace Frank Richardson, [24] son in law of William Sommers, and son of John Richardson, previous occupier of the earlier dwelling in the 1870s. Further improvements were made during Richardson's ownership, including new outbuildings in 1915 designed by the architects, Seeley, King and Everett. [25]

Evolution of the Landscape Setting

A plan of the Barrarabool Parish by Andrew McWilliams in 1861 showed the extent of the setting associated with "Kardinia House" during Alexander and Barbara Thomson's occupation. The historic photograph of 1866 and paintings by Webb in the 1870s also give some idea of the landscape at that time.



A. McWilliams, Extract of the Parish of Barrabool Plan, 1861, showing "Kardinia".

Source: Jennifer Bantow, Geelong.

A major transformation of the setting came with the ownership of William Sommers. Extensive improvements were reported in the Geelong Advertiser on 31 October 1884. They included an irrigation system, a maize patch of 2 acres 'on the slope of the hill at the rear of the house', a 6-acre apple orchard with 1000 new apple trees, the orchard overall comprising 15,000 fruit trees.[26] A natural lagoon and trees were also laid out to the east of "Kardinia". The extent of the setting is shown in the plan of the Kardinia Estate (c.1890) as outlined in the Statement of Recommendation and landscape remnants are also shown in aerial images by Charles Pratt. A company had been formed to subdivide the southern parts of the Kardinia Estate (the paddocks seen in the background of the Norton photo of c.1866) into 250 allotments. Directors of the Kardinia Estate Company were William Sommers, William Higgins, W.P. Carr, T. Fender, H. Howard, F. Drew, H.P. Douglas, H.F. Richardson (secretary) and F.J. Leary (auditor).[27] The remaining seventeen acres (6.88 hectares) were retained by H.F. Richardson.[28]

х



Aerial view looking east showing "Kardinia House" and its setting, c.1925.p Note the tree-lined drive which terminated as a loop in front of the house. Also note the 'back drive' which still exists today and is not part of the proposed registration. Source: C. Pratt, Accession H91.160/591, State Library of Victoria



Figure 1. The house photographed in 1979. Source: State Library of Victoria.

References

- [1] Geelong Advertiser, 16 November 1847, p.1.
- [2] Ibid., 6 June 1844, p.1.
- [3] Ibid., 17 December 1845.
- [4] Geelong Council Rate Book, entry 364, 1850, Geelong Heritage Centre collection.
- [5] Ibid., entry 67, 1852.

[6] Geelong Advertiser, 19 November 1852, p.1.

[7] D. Rowe, About Corayo: A Thematic History of Greater Geelong, City of Greater Geelong, 2021, pp.500-501.

[8] Geelong Council Rate Book, op.cit., entry 816, 1853.

[9] Ibid., entry 81, 1854.

[10] See South Barwon Rate Books, 1870-1880, Geelong Heritage Centre collection. See also Births, Deaths and Marriages Victoria https://www.bdm.vic.gov.au/ and L. Gardiner, 'Alexander Thomson (1898-1866)', Australian Dictionary of Biography, National Centre of Biography, Australian National University, https://abd.anu.edu.au/biography/Thomson-alexander-2731/text3853, published first in hardcopy 1967, accessed online 22 April 2024.

[11] South Barwon Rate Books, op.cit.

[12] South Barwon Rate Books, op.cit., 1881-1890.

[13] Ibid., 1882-87.

[14] D. Rowe, 'Architecture of Geelong 1860-1900', B.Arch. thesis, Deakin University, 1991, vol.1, p.13.

[15] Ibid., vol.2, sheet 139.

[16] Rowe, About Corayo, op.cit., p.677, 1072.

[17] Rowe, 'Architecture of Geelong', opl.cit., sheet 163.

[18] Geelong Advertiser, 24 December 1881, p.3.

[19] Ibid., 16 August 1881, p.3.

[20] Rowe, 'Architecture of Geelong 1860-1900', op.cit., vol.1, p.3.

[21] Geelong Advertiser, 2 July 1889, p.3.

[22] Ibid., 23 January 1884, p.3.

[23] Rowe, About Corayo, op.cit., p.1122.

[24] South Barwon Rate Book, op.cit., entry 240, 1890-91.

[25] Geelong Advertiser, 30 October 1915, p.3.

[26] Geelong Advertiser, 31 October 1884.

[27] D. Rowe, 'City of Greater Geelong Belmont Heritage Areas Report', vol.1, prepared for the City of Greater Geelong, August 2007, p.46.

[28] Ibid.

xii

Set of plans from 1979 (Wah J. Source: State Library of Victoria):



Figure 2. Front Elevation of the house.




Figure 4. Ground floor plan of the house.



Figure 6. Section of the house.

Figure 3. Side elevations of the house.




Figure 5. First floor plan of the house.




Figure 7. Selected decorative detailing of the house.

2 Physical Analysis

2.1 Introduction

The following section of the CMP is based upon a physical survey of the heritage place and investigation of available documentary evidence, including all available plans of the building, maps, photographs, and newspaper articles that are known to exist. An external and internal survey of the place was conducted on 14 May 2024. The results are summarised in the site survey datasheets.

2.2 Site Context

The heritage place, located at Belmont, Geelong, is bound by Riverview Terrace to the west, the Barwon River Holiday Park to the east, and a row of detached houses (7 to 25 Riverview Terrace) and the Geelong Bowls Club to the south. The place overlooks Barrabool Road and Barwon River to its north. The place is trapezoidal in shape, with a long, narrow road projecting from its southeastern corner.

2.3 Site Plan

The heritage place comprises a Victorian period house with additions and alterations set in a large site comprising a front sloping landscape with return driveway and mature trees. Prominent postwar buildings dominate the rest of the site to the east and south.

2.4 The House

The house is a double-storey Victorian period residence built in stages over 1855-1880, with later additions and accretions that have completely overwhelmed and concealed any traces of the original 1855 stone house. As acknowledged by the original citation, the house has been extended 'beyond recognition' from the original house occupied and associated with Alexander Thomson. The current house owes its appearance to the alterations by Geelong businessman H.F.Richardson. The ground level however retains original bay window front of the attic level house that was built and inhabited by Thomson.

2.5 Interiors

The interior has been heavily altered, however there are traces of the late Victorian decorative scheme including some architraves, ceiling roses, cornices and fireplaces. There are no traces of original wallpaper or furnishings.

2.6 Outbuildings

There is a timber outbuilding joined to the rear of the house by a covered breezeway (Figure 14). It has been heavily altered in the post-war period and late twentieth century by conversion into office spaces and reception area (Figure 15). Historical aerial view of 1925 shows the early twentieth century configuration of outbuildings to the rear, none of which survive apart from remnants of a small northernmost section of the attached timber outbuilding.

2.7 Additions

The house has been extended in the post-war period with the addition of various rooms and additions to the side and rear. There is a rendered brick square flat roofed room added to the southeast (Figure 25). A red brick double storey wing has been added to the southwest with a pitched roof and a further single storey extension to the south (Figures 19, 22). Along the south of the courtyard is another post-war flat roofed addition with aluminium framed glazing and sheet walls (Figure 20).

xiv

2.8 Other buildings

Around the house to the east, south and west are post 1960s brick buildings that were associated with its use by the Salvation Army. These are vernacular brick buildings with flat iron roofs.

3 Site Survey Data Sheets

The following data sheets refer to each of the rooms of the Victorian period (Main) house below. The rear addition rooms and spaces were also inspected (W).

3.1.1 Victorian Period (Main) House

Room Condit 1 Riverview		mont (Kardinia House		Date Surveyed	14 May 2024			
Room No.	1	Room Name	Corridor	Surveyed by	JY			
Use	Main hous	se entryway / corridor						
Ceiling								
Coning	Divided into 2 bays Northern bay:							
			rose painted	in dusty pink, cream, pist	achio with gold			
	detailing		, ,		3			
	0	acks and bubbling paint	observed					
	Southern							
	Dropped,	non-original, plain ceiling	g with access h	natch				
	No mouldi	ng and ceiling rose, poo	r paint job con	npared with northern bay				
Walls			[,] pink at top, lig	ght dusty pink at bottom				
		at the top part of walls						
		int suggests an inner lay						
		and architraves are of da		colour				
		al handrailing affixed to						
			outhern bay ha	s paneling in dusty pink a	nd cream with			
	gold detailing to its underside							
	Chamfered corners at archway							
	Curtain rod brackets above archway and door openings							
	Early light switch overpainted in dusty pink Arched doorway to 8 blocked by a large, plain bulkhead							
	Damages observed at architraves and lower parts of walls							
Floor								
Doors	Non-original carpet 2x external doors – front door to driveway; back door to courtyard							
Doors	Front door:							
	Single swinging timber door with transom and sidelights							
	Transom has textured, transparent glazing							
	Top sidelights next to the transparent glazing							
	Middle sidelights have textured, transparent glazing							
	Below the middle sidelights are timber-boarded							
	There are curtains for the sidelights							
	The 4-panel door is painted in deep bronze green on the outside and has non-original							
	fixtures and door knob							
	It is painted in deep dusty pink internally							
	Back door:							
	Single swinging, windowed timber door with a glazed panel in the top 2/3 part							
	The window has a large, central glazing and 10x small, narrow side glazing bordering it							
	The door is painted in white on the outside and has a non-original door handle and hinge							
	It is painted in deep dusty pink internally							
	3x internal dears 1x to 2: 1x to 4: 1x to 7							
	3x internal doors – 1x to 2; 1x to 4; 1x to 7							
	Generally, all 3x doors have very deep doorways and a single swinging, 4-panel timber door at the end of the wall							
	Painted in dark and light dusty pink							
	Non-original door knob and push plate							
Windows	N/A							
Significant		ouldings and rose						
Items		orway and ornaments						
	Front door							
	Back door							
	Architrave	s, internal doors, skirting	IS					







Figure 13. Ceiling rose detail.

Room Condit				Date Surveyed	14 May 2024			
		(Kardinia House						
Room No.	2	Room Name	Board room	Surveyed by	CM			
Use	Board room							
Ceiling	Pressed metal,	Pressed metal, except at bay window which is plaster						
_	Pressed metal of	cornice – except a	t bay window					
	Later light fitting							
	Hole at centre -	- former light fitting	g removed					
		peeling paint to d	cornice					
Walls	Painted plaster							
	Covered wall ve							
	Vent near chim							
		g to bay all aroun						
		to timber panelling	9					
		Skirtings different again						
Floor	Carpet (new) or							
Doors		doors to rooms 1						
			g stop block at base	e				
Windows		indow, double hur	ng sliding sash					
Significant	Ceiling – presse							
Items		mber joinery and	windows					
	Vents							
Intrusive	AC units							
Items	Floor							
0.1	Conduits and fix							
Other		e and mantle, cov	ered fire box					
Features	Picture rail							
	Curtains (non o	• /	nauto of the house o	and many he remainduction	-			
Notoo	NA		parts of the house a	and may be reproductio	1			
Notes		<u></u>						
Significance	Primary Signific							
Integrity Disease	Medium integrit	у.						
Photos								




Figure 14. View of the boardroom.



Figure 16. Detail view of the ceiling within bay window.




Figure 15. View of the boardroom with fireplace.



Figure 17. Detail view of the pressed metal ceiling.

	(Kardinia House	e)	Date Surveyed	14 May 2024		
3	Room Name	Staff room	Surveyed by	JY		
Kitchen and sta	aff lunch room	1				
Dropped plaste	rboard ceiling in a	a gridded tile	pattern (painted in white)			
Has 1x access	hatch	-				
Original/early c	ornices partially c	oncealed				
	walls with crown	moulding and	l picture rail moulding (pain	ted in white and		
•	dusty pink, some	e partially cove	ered by vinyl coverings that	t come up to the		
		dow				
			2 (board room)			
		/enings				
		rd room)				
Dropped ceiling	1					
Kitchen fit-out						
Server box						
Architrave and	door to 2					
Skirtings						
Redundant ligh	ting and wiring					
1x mirror at we	st wall					
Medium to Low	1					
Figure 18 View						
	3 Kitchen and sta Dropped plaster Has 1x access Original/early c Top part of the mint green) Walls are crear Parts of the wa Skirtings are in walls 1x wall hatch a Wall hatch to th Wall-mount ser Non-original miding 1x timber 4-part 1x north-facing trices North-facing trices North-facing trices North-facing trices Comped ceiling Kitchen fit-out Server box Architrave and Skirtings Redundant light 1x mirror at we N/A Secondary Signt Medium to Low	errace, Belmont (Kardinia House3Room NameKitchen and staff lunch roomDropped plasterboard ceiling in aHas 1x access hatchOriginal/early cornices partially ofTop part of the walls with crownmint green)Walls are cream coloured with wParts of the wall to the north andSkirtings are in dusty pink, somewalls1x wall hatch above the east winWall hatch to the south wallWall-mount server box affixed allNon-original mint green vinyl cov1x timber 4-panel door to 2 (boa1x north-facing tripartite windowin the centre1x east-facing double-hung sastNorth-facing tripartite windowDropped ceilingKitchen fit-outServer boxArchitrave and door to 2SkirtingsRedundant lighting and wiring1x mirror at west wallN/ASecondary SignificanceMedium to Low	errace, Belmont (Kardinia House) 3 Room Name Staff room Kitchen and staff lunch room Dropped plasterboard ceiling in a gridded tile Has 1x access hatch Original/early cornices partially concealed Top part of the walls with crown moulding and mint green) Walls are cream coloured with water ingress t Parts of the wall to the north and east are tiled Skirtings are in dusty pink, some partially cover walls 1x wall hatch above the east window Wall-mount server box affixed above door to 2 Non-original mint green vinyl coverings 1x timber 4-panel door to 2 (board room) 1x north-facing tripartite window with fixed gla in the centre 1x east-facing double-hung sash window com North-facing tripartite window Dropped ceiling Kitchen fit-out Server box Architrave and door to 2 Skirtings Redundant lighting and wiring 1x mirror at west wall N/A Secondary Significance Medium to Low	Belmont (Kardinia House) Staff room Surveyed by 3 Room Name Staff room Surveyed by Kitchen and staff lunch room Dropped plasterboard ceiling in a gridded tile pattern (painted in white) Has 1x access hatch Original/early cornices partially concealed Top part of the walls with crown moulding and picture rail moulding (pain mint green) Walls are cream coloured with water ingress to the east wall Parts of the wall to the north and east are tiled for kitchen splash back Skirtings are in dusty pink, some partially covered by vinyl coverings that walls 1x wall hatch above the east window Wall hatch to the south wall Wall-mount server box affixed above door to 2 (board room) Non-original mint green vinyl coverings 1x timber 4-panel door to W16 1x timber 4-panel door to 2 (board room) 1x north-facing tripartite window with fixed glazing on the sides and a do in the centre 1x east-facing double-hung sash window converted into a hopper window North-facing tripartite window Dropped ceiling Kitchen fit-out Server box Architrave and door to 2 Architrave and door to 2 Skirtings Redundant lighting and wiring 1x mirror at west wall N/A Secondary Significance		

хх



Room Condit	ion Survey errace, Belmont (Kardinia Hou		Date Surveyed	14 May 2024				
Room No.	4 Room Name		~	Surveyed by	 CM			
		AILIOO	Π	Surveyed by	CM			
Use	Art room							
Ceiling	Painted ceiling							
	Some small cracks – all direction							
	Elaborate cornice – possibly ad	ded to, som	e cracks					
	No cornice to bay window							
	Big ceiling rose – looks later							
	Overall, seems to be in a good	condition						
Walls	Plaster, painted							
	Picture rail							
	Some minor cracks	a naasihlu	haaayaa af	furniture				
	Damage to archway – both sides, possibly because of furniture							
Floor	Timber paneling below windows							
FIUUI	Later carpet Skirtings look later							
Doors	Original timber panel door to corridor and next room							
DOOIS	Later hardware, poorly painted							
	Frames possibly original							
Windows	Bay window – 3x double-hung sash							
Williaow3	Single double-hung sash							
	All windows have the same architrave detailing, possibly some original hardware							
Significant	Decorative plasterwork		inig, pecci	ny como originarria	anaro			
Items	Arch to bay							
	Doors and windows							
	Fireplace							
	Paneling below windows							
Intrusive	Carpet flooring							
Items	Picture rail							
	Decide – skirtings, compare with other rooms							
	Light fittings							
Other	Marble fireplace – blocked up							
Features								
Notes	Overall good condition and could be restored.							
	Some skirtings may be reproductions.							
Significance	Primary							
Integrity	High to Medium							
Photos								

xxii





Figure 21. View of room including bay and ceiling rose.



Figure 22. Marble fireplace.



Room Condit		(Kardinia House)	Date Surveyed	14 May 2024		
Room No.	5	Room Name	Surveyed by	СМ		
Use	Classroom and kitchenette					
Ceiling	Painted plaster					
5	Later cornice, ve	ery simple				
	Later lights	, . ,				
	No ceiling rose					
	Minor cracks ev					
		vindow, higher ceiling lining w	ere in			
Walls	Painted plaster					
		er / moisture damage at south	west corner, low			
	Several covered					
		except at southwest)				
		or frame architrave different fro				
		g to bay frame opening and be	elow windows			
Floor	Fire place – late Carpet over					
FIOOP		sture at southwest corner				
	Probably timber					
Doors		I timber panelled door to room	1 – later architrave			
DOOIS		loor to room 6 – possibly later				
Windows	Bay – 3 window		opening but name not too n			
Significant	Overall form / la					
Items	Fireplace opening					
	Bay window + panelling + opening + windows + joinery					
	Consider – skirtings and architraves					
Intrusive	Timber fire place					
Items	Cornice					
	Light fittings					
	Carpet					
	Later door					
Other	Covered wall ve	nts are interesting				
Features						
Notes	Altered but legible Cracks in walls are minor, moisture damage will need to be addressed.					
	Cracks in walls	are minor, moisture damage v	vill need to be addressed.			
	Primary Signific	ance				
Integrity Photos	Medium					
Photos						
			A			
		1111/111 Contraction				
		T HALAN ALL AND THE THE REAL OF	ANT -			
				-		
	10 10 1					
	131					
			Line water			
	A STATE		E I			
		174				
			The second se			



Room Condit		ont (Kardinia House)		Date Surveyed	14 May 2024		
Room No.	6A	Room Name	Corridor	Surveyed by	СМ		
Use	Corridor						
Ceiling	Painted plast	er					
ooning	No cornice						
Walls		er, peeling and with a	ir				
		along east wall					
		er and mixed, south is	smaller and dif	ferent			
	Handrails	,					
Floor	Carpet						
Doors	Later panel to	o room 5					
	Original pane						
		ly panel to 6B with or	iginal hardware				
		altered opening to rea					
Windows	N/A	, 0	1				
Significant	Architraves						
Items	Door opening	to courtyard					
	Door to 6B	. ,					
Intrusive	Handrail						
Items	Curtains						
	Later doors to south courtyard (but not the openings)						
	Carpet	<i>,</i> (- ·			
	Telstra box						
	Light fittings						
Other	Fire extinguis	hers					
Features	Ŭ						
Notes	Couldn't lift the carpet, would be interesting to see the floor below						
	Lots of potential in both rooms to reinstate an earlier arrangement / appearance						
	Space of prin	nary significance, me	dium to low integ	grity.			
Significance	Secondary						
Integrity	Low						
Photos							



xxvi

Room Condit		nt (Kardinia House)		Date Surveyed	14 May 2024			
Room No.	6B	Room Name	Bathroom	Surveyed by	CM			
Use	Bathroom							
Ceiling	Board or panel with texture and paint							
Cennig	No cornice							
Walls	Painted plaste	r						
Trano		re damage and spall	lina					
	Evident at sou	th wall under window	N					
	Small storage	cupboard at fireplac	e location					
		out, tiles behind						
	Damage to pla	ster at side of chimr	ney breast					
Floor	Vinyl – with ste	ep up to wet area						
Doors	Very thin early	door to 6A						
	Low							
Windows		ng, altered glazing to	o south					
Significant		glazing top sash						
ltems	Door to 6A							
Intrusive		hand basin etc.						
Items	Later step in fl							
		replace – reinstate fi	replace					
	Light fitting							
Other	Flooring	ly built out from wall						
		5						
Features	There is tile behind, suggesting an earlier bathroom arrangement Tiles for skirting near basin							
Notes			d altorad					
NOLES	Looks like a nice room, divided and altered Need to address damp							
	Exterior vents may be covered – check							
		nstate an earlier arra		arance				
Significance	Secondary		angement / appe					
Integrity	Low							
Photos								



Room Condit 1 Riverview 1	tion Survey Ferrace, Belmont (K	(ardinia House)		Date Surveyed	14 May 2024			
Room No.	7	Room Name	Office	Surveyed by	JY			
Use	Office							
Ceiling	Plain, dropped cei	ling						
-	Cornice around ce	iling						
	Access hatch to th							
	Light tubes affixed							
Walls	Top part painted in							
	Separated by a mo							
	Bottom part painte							
	Skirtings painted in An area next to the							
	Early light switches			ιþ				
	Hairline cracks ab							
	Lower part of sout			ae				
	Two wall vents on							
Floor	Grey carpet							
Doors	, <u>,</u>	doors in deep du	sty pink and o	cream, with original architra	ave and non-original			
	door knobs							
	Northern door to 1 (corridor)							
	Southern door to 6A							
Windows	1x north-facing tripartite window with fixed glazing on the sides and a double-hung sash in the							
	centre							
	Floor to ceiling window frame painted in deep dusty pink and cream Peeling paint and wood rot at lower areas of the frame, concealed by duct tape							
Significant	Fireplace and mar			frame, concealed by duct	lape			
Items	Tripartite window	lile						
itemo	Architrave, doors,	and skirtings						
Intrusive	Dropped ceiling	and onliningo						
Items	Wall panelling							
Other	1x decommissione	ed fireplace to the	e west, chimn	ey breast extant				
Features	Mantle is made of black and white marble							
	Fireplace is made of cast iron							
	Area immediately below fireplace is of patterned tiles							
Notes	Water ingress pres	sent at the wall b	etween 6A ar	nd 7				
Significance	Primary							
Integrity	Low							
Photos								





Room Condit	ion Survey ferrace, Belmont (k	(ardinia Houso)		Date Surveyed	14 May 2024					
Room No.	8 and 9	Room Name	G/F stairwell and 1/F stair hall	Surveyed by	JY					
Use	Stairwell to 1/F with under-stair storage and 1/F stair hall									
Ceiling		Plain ceiling								
Walls	Painted in cream									
	Doorway to 1 (cor	ridor) – refer to re	oom condition surve	y for 1						
	Doorway to 1 (corridor) – refer to room condition survey for 1 Built in cupboard next to the under-stair storage Skirtings are comparatively less ornate than the main house									
	Skirtings are comp	paratively less or	nate than the main h	ouse						
Floor	Dark grey carpet									
Doors			n original lock and kr							
			n the inside, white or							
			hitraves and door du							
Windows			n 6 panes of textured							
			th curtain rod bracke							
			a dark, hardwood h	andrail matching the	e stair balustrade and					
	above, a modern r		/							
Cignificant			/F appears to be in g	good condition						
Significant Items	Staircase including	g balustrade, trea	ads, spandrei							
items	Sash window									
	Stained glass wind	woh								
Intrusive	Contemporary me									
Items	Redundant lighting									
	Carpeting and nor									
	Top of stair gate									
Other	Under-stair cupbo	ards painted in c	ream							
Features	Staircase spandrel with decorative panelling									
		Considerable wear-and-tear at spandrel and cupboard due to high use								
			to the top balustrade							
Notes			d east walls causing		moulding					
	Skirting near door	is detached from	n the wall		-					
Significance	Primary									
Integrity	Hight to Medium									
Photos	MAR									



ion Survey errace, Belmont (Kardinia House)		Date Surveyed	14 May 2024		
Courtyard Room Name	Courtyard	Surveyed by	CM		
Courtyard					
N/A (open-air courtyard)					
Verandah roof to main house is cor	rugated iron				
To red brick the ceiling is timber lini	ng board				
Weatherboard					
)			
	oth, some rough				
	han / alamad				
		ha blugatana thrach			
			JIU		
			v original		
			x original		
	antea				
	n house				
A boat is placed in the passage					
Unusual wall finish partly rough and	I partly smooth				
Odd at left window, looks like the sr	nooth wall has been	cut out			
LOW					
	CourtyardRoom NameCourtyardN/A (open-air courtyard)Verandah roof to main house is cor To red brick the ceiling is timber liniWeatherboardRed brickGlazing (metal sheet to the narrow Stone / render painted – some smo Evidence of damp to rough wallsPaving Central element and two drains with Later doors to additions Original openings with panelled time 	CourtyardRoom NameCourtyardN/A (open-air courtyard)Verandah roof to main house is corrugated iron To red brick the ceiling is timber lining boardWeatherboard Red brickGlazing (metal sheet to the narrow passage to the west Stone / render painted – some smooth, some rough Evidence of damp to rough wallsPaving Central element and two drains with standing water Later doors to additionsOriginal openings with panelled timber / glazed Door with bluestone threshold – altered frame and mayl Other door is later, later opening but possibly original lin Main house – tripartite window with bluestone sill; single sash but altered to p sash, all overpainted Later window for extensionsWindows and door openings to main house Arrangement / connection to courtyard VentsLater extensions and doorsA boat is placed in the passageUnusual wall finish partly rough and partly smooth Odd at left window, looks like the smooth wall has beenSecondary significance (historical)	Courtyard Room Name Courtyard Surveyed by Courtyard N/A (open-air courtyard) Verandah roof to main house is corrugated iron To red brick the ceiling is timber lining board Weatherboard Red brick Glazing (metal sheet to the narrow passage to the west) Stone / render painted – some smooth, some rough Evidence of damp to rough walls Paving Central element and two drains with standing water Later doors to additions Original openings with panelled timber / glazed Door with bluestone threshold – altered frame and maybe bluestone threshol Other door is later, later opening but possibly original lintel Main house – tripartite window with bluestone sill; single window possible 1: sash but altered top sash, all overpainted Later window for extensions Windows and door openings to main house Arrangement / connection to courtyard Vents Later extensions and doors A boat is placed in the passage Unusual wall finish partly rough and partly smooth Odd at left window, looks like the smooth wall has been cut out		





Figure 27. View south.

Room Cond 1 Riverview	ition Survey Terrace, Belmont (K	ardinia House)		Date Surveyed	14 May 2024
Room No.	10	Room Name	Corridor	Surveyed by	JY
Use	1/F corridor that ov	erlooks the cour	tyard		I
Ceiling	Dropped ceiling				
	Access hatch near		original ceiling		
Walls	Cream coloured w				
	Skirtings in deep dusty pink and less ornate than those on G/F				
	Vents to the top part of the walls on both sides				
Floor	Dark grey carpet				
_	Slopes up when approaching 12A and 12B				
Doors	Close to 9 is an arched doorway with chamfered corners and the top part boarded up Matching doors to 9, 14, 15 with deep dusty pink architraves – timber 4-panel single swi				•
			ep dusty pink ar	chitraves – timber 4-pan	el single swinging
	door painted in cre		doonwoy with a	appendent of the fit	tod with a nan
	Close to 12A and 12B is an arched doorway with chamfered corners, it is fitted with a r original glass door, cracks are observed at the corner of the wall				led with a non-
Windows					urtvard
Window3	3x equally spaced, identical double-hung sash windows overlooking the courtyard Southernmost window (closest to 12A and 12B) has a broken rope				
	Middle window has				
	Northernmost wind				
	Lace curtains and				
Significant	Concealed ceiling				
Items	Doors to 9, 14, 15				
	Chamfered, archeo		luding later elem	ents)	
	Architraves and sk	0			
	3x double-hung sa	sh windows			
Intrusive	Dropped ceiling				
ltems	A/C unit				
	Light tube and wiri				
	Non-original glaze				
	Board concealing a	arched doorway			
	Lace curtains				
	Carpet	nont			
	Fire escape equipr	nent			

Other	N/A
Features	
Notes	Windows provide views to weatherboard annex roof
Significance	Primary
Integrity	Medium to Low
Integrity Photos	

	tion Survey	nt (Kardinia House)	Date Surveyed	14 May 2024
Room No.		Room Name	Surveyed by	СМ
Use	Storage			
Ceiling	Painted, no co	rnice		
eening	Probably lowe			
Walls	Painted plaste			
		ne to east wall		
	Some patch re			
	Covered vents			
		ked up or plastered over		
		rent again but they look right		
Floor	Carpet			
	Possibly timbe			
Doors		anel door to room 9		
	Altered and la			
	Architraves lo			
Windows		ble hung sliding sash with deep	b timber reveal	
		id panel and upper panes		
0'	Unsure about	Inat		
Significant	Window			
ltems	General arran	gement		
	Door			
	Joinery Maybe skirting			
Intrusive	A/C and pipev			
Items	Dropped ceilir			
items	Light fixtures	9		
	Conduits			
	Alteration to w	indow		
	Whiteboard			
Other	Musty smell			
Features	,			
Notes	Fairly plain roo	om, decorative elements strippe	ed out	
	Hatch in ceilin	g might have some original det	ails hidden	
	Space second	ary significance. Low integrity.		
Significance	Primary			
Integrity	Low			
Photos		A CONTRACTOR		-
		and the second se	-	
	The A			· · · · ·
	and the second second			
	and the second second			
		the second se		
	States and States			
	ACCOUNTS OF T	The second s		
	100000000000000000000000000000000000000	A DESCRIPTION OF THE OWNER OF THE		
	5-11			
	1			-TL
	-			
		the second se		



1 Riverview T	ion Survey errace. Belmont	(Kardinia House)		Date Surveyed	14 May 2024
Room No.	12A & 12B	Room Name	N/A	Surveyed by	JY
Use				the red brick rear addition	
Ceiling		ntains the original c	eiling with cornice	es, an access hatch show	vs timber slats above
	the ceiling 12B has a drop	ped ceiling with light	t tubes and smoke	e detectors	
Walls	Cream painted				
	Skirtings in dee				
	Arched doorway	top part of the west	wall		
		ar doorway to red b	rick building A		
Floor	Dark grey carpe	t, floor level higher	than that of 10		
Doors				tted with a non-original g	
				am, with deep dusty pin with plain door frame, le	
	stairs	uoor to south wall (p	bainteu în creani),		
Windows		unched window wit	h aluminium fram	e	
Significant	Original ceiling				
Items	Architrave and o				
Intrusive Items	Non-original dro South door to e	xternal fire stairs			
	Punched windo				
	Doorway to red	brick building			
Other	Carpet N/A				
Features	IN/A				
Notes	N/A				
Significance		Space Secondary (L	ow integrity)		
Integrity Photos	Low				

Room Condit 1 Riverview T	ion Survey errace, Belmont (M	(ardinia House))	Date Surveyed	14 May 2024
Room No.	13	Room Name	Office	Surveyed by	JY
Use	Office				
Ceiling	Original white-pair Contains ceiling ro				
Walls	Cream painted wa Chimney breast or Fireplace decomm Two-toned walls m Cracks to walls co 4x wall hatches – 2	n east wall rema hissioned hatching other ro nnecting to the r	ooms neighbouring ro	om 14	
Floor	Dark grey carpet				
Doors	1x timber 4-panel 12A and 12B	single swinging	door painted in	cream, with deep dusty p	oink architraves, to
Windows	1x tripartite windo	w with the centra	al sash window	converted into a hopper v	window
Significant	Tripartite window				
Items	Ceiling cornice and	d rose			
Intrusive Items	N/A				
Other	N/A				
Features					
Notes	N/A				
Significance	Primary				
Integrity	Medium				
Photos	N/A				

Room Condi 1 Riverview	tion Survey Terrace, Belm	iont (Kardinia House)		Date Surveyed	14 May 2024
Room No.	14	Room Name	Office	Surveyed by	JY
Use	Office with 2	1 cubicle partitions			ł
Ceiling		iling with light tubes, pl	ain without corni	ce	
	Cuts throug	h original wall vent			
Walls		ured with deep dusty p	ink skirtings		
F leen		s to the west wall			
Floor Doors	Dark grey c	arpet panel single swinging	deer painted in a	room with doop ducty	nink architrayon to
DOOIS		ly door knob		ream, with deep dusty	pink architraves, to
Windows		uble-hung sash window	v with elaborate a	architrave painted in lig	ht dusty pink.
		cess to the verandah			···· ··· · · · · · · · · · · · · · · ·
		indow has a later swing		externally	
Significant		g sash window and arc	chitrave		
Items	Skirting				
	Timber door	ſ			
Intrusive	Cupboard	l nining			
Intrusive	A/C unit and				
1.61113	Lighting and wiring Screen door				
Other		the north of the door,	white painted wi	th deep dusty pink arc	nitraves
Features					
Notes	Holes on so				
	Cracks alon	g the west and south v	valls		
<u></u>					
Significance					
Integrity Photos	Low		1.		

xl

Room Condi 1 Riverview		nt (Kardinia House)	Date Surveyed	14 May 2024
Room No.	15	Room Name	Surveyed by	СМ
Use	Office		L	
Ceiling	Painted			
U	No cornice			
	Dropped			
Walls	Painted plast	er		
	Crack to wes	t wall		
	Crack at sout	heast corner		
		ge along east		
	4x wall vents			
	Skirtings as p			
	Decorative de			
		oor – 4 bricks thick		
Floor	Carpet			
Doors		nal door to room 9, early hardwa	re, thicker, normal compared	d to room 11
	Decorative a			
Windows		randah – locked, goes to floor	- sister - I	
0'		with decorative architrave, looks	original	
Significant	Joinery			
ltems	Window, doo Vents	S		
		d		
Intrusive	Wall cupboar	u		
Intrusive	Lights Conduits			
litems	Carpet			
	Lowered ceili	na		
	AC unit	ing		
Other	Wall cupboar	d – early		
Features		altered to suit		
i outuroo		vall, stepped, near cupboard		
Notes	No evidence			
	Nice room	1		
	Space Secon	dary significance. Low integrity.		
Integrity	Low			
Significance				
Photos				
	ley]	-		Y
				-
		C.		

1 Riverview 7	tion Survey Ferrace, Belmont	t (Kardinia House)		Date Surveyed	14 May 2024	
Room No.	16	Room Name	Verandah	Surveyed by	СМ	
Use	Verandah					
Ceiling	Verandah roof	galvinated iron				
•	Some rust	-				
Walls	Condition good	, overpainted tuck	pointing with over	painted bluestone quoi	ning.	
	Vents to rooms	visible				
Floor	Metal deck					
Doors	N/A					
Windows		hed verandah in bi	rick / stone above	the flat parts of the sid	e gables.	
Significant	Vents					
Items	Lacework					
Intrusive	AC units					
Items	Floor	· · · ·				
Other		ome decay to panel	over bay window	Ι.		
Features	4x ports and tin					
Nataa	One balustrade					
Notes	Not really accessible, a bit dangerous Primary Significance, Medium integrity.					
		cance, Medium Inte	grity.			
Integrity	Medium					
Significance Photos	Primary	No. No. 700 (100 (100 (100 / 100 / 100 / 100 / 100 / 100 / 100 / 100 / 100 / 100 / 100 / 100 / 100 / 100 / 100	1 THERE A			



4 Significance

The heritage place is identified to have cultural heritage significance on both state and local levels and hence placed on statutory listings. It is also recognised by non-statutory listings such as the National Trust of Australia (Victoria) heritage register.

4.1 Victoria Heritage Register

The heritage place is listed on the Victorian Heritage Register (VHR) as VHR H0337 Kardinia House.



4.1.1 Statement of Significance

The latest Statement of Significance for the place is prepared as part of Heritage Victoria's *Statement of Recommendation from the Executive Director* in March 2024. It is reproduced as follows:

What is significant?

Kardinia House, a two-storey brick and stone house, constructed in various stages, the original stone structure being constructed in 1854 and additions made in 1869 and again in the 1880s. Significant later additions include the bay windows and cast-iron verandah during the 1880s. The house occupies an elevated and commanding position with an outlook towards the Barwon River. Several mature exotic trees survive from the nineteenth century garden.

How is it significant?

The Kardinia House is of historical significance to the State of Victoria. It satisfies the following criterion for inclusion in the Victorian Heritage Register:

Criterion A

Importance to the course, or pattern, of Victoria's cultural history.

Criterion H

Special association with the life or works of a person, or group of persons, of importance in Victoria's history.

Why is it significant?

Kardinia House is historically significant as one of the oldest residences in the Geelong region. The original stone house (1850-1855) is still present, though it was extended and renovated from the 1860s to 1880s. The house predates the gazettal of the township of Geelong and has a position of prominence within the landscape with views from the house to the Barwon River as well as views of the house from across the river. Kardinia House has a long and varied history and is associated with several influential Victorians and

xliv

organisations. After pioneer colonist Dr. Alexander Thomson, subsequent owners included other local and colonial politicians, cementing Kardinia House's place at the centre of high society in the region. From 1947 to 1986 the House was used as a children's home for the Salvation Army, reflecting the decline of opulent living, and the subsequent adaptation of large, colonial homes for public use. [Criterion A]

Kardinia House is historically significant for its association with the pioneer colonist, politician, churchman and patriarch, Dr. Alexander Thomson, one of the founders of Geelong. Thomson's career is interwoven with the history of Geelong and the infant Port Phillip colony. Thomson was an influential Victorian, campaigning for Victoria's separation from New South Wales, being elected twice to the new colony's Parliament, serving as Geelong's first mayor, and becoming director of the Geelong-Melbourne Railway Company. Kardinia House, with its commanding and elevated position overlooking the Barwon River and surviving mature plantings, is demonstrative of Thomson's status and his close relationship with the Geelong region, being one of the township itself. [Criterion H]

A 1974 Statement of Significance, prepared as part of the Register of the National Estate, is also available on the Victorian Heritage Database website, as follows:

In 1836 pioneer Victorian settler Dr. Alexander Thomson, former medical officer with the Port Phillip Association, took up land at Geelong on the Barwon River. Kardinia, the two storey brick and stone house which now stands on this first site, was constructed in various stages with the stone house replacing the original timber structure between 1850 and 1855. The extensive additions were made prior to1869 with the verandah dating from the later 1880s. Kardinia stands on one of the first settled and most historic homestead sites in the Geelong region, that of the legendary pioneer colonist, politician, churchman and patriarch, Dr. Alexander Thomson. The career of this remarkable and altruistic man is interwoven with the history of Geelong and the infant Port Phillip colony. The present homestead, of uncertain date, contains within the fabric the stone house of 1850-55, later extended beyond recognition c 1890 by H.F. Richardson, Geelong businessman. Kardinia has been converted as a children's home for the Salvation Army. The building is recognisably intact externally, but the late 1880s interior has been largely obliterated. The structure is of low integrity.

The following text was recommended by the Heritage Council to be added to the Statement of Significance on 6 June 2024:

"Thomson was heavily involved in requests for the 'protection' of the newly arrived squatters which came at the expense of the Wadawurrung People. Ultimately, his usurping of Wadawurrung Country (to use the words of Fred Cahir) and grazing of cattle and sheep helped end the Traditional way of life for Wadawurrung People in Greater Geelong. With regard to associations with the Wadawurrung People, no explanation has been given for the Indigenous name of the property, "Kardinia", an explicit meaning being 'morning' or 'sunrise'. Thomson established "Kardinia" on the south bank of the Barwon River. To the Wadawurrung, this waterway is known as Barwong (Barri Warri Yaluk) – the great river (Yaluk) that runs from the Otway Ranges (Barri – mountains) in Eastern Maar Country (the place of the Gadubanud and Gulidjan Peoples) into Wadawurrung Country and enters the sea (Warri) at Barwon Heads (the place where the salt and fresh waters mingle)."

4.2 **Permit exemptions**

The heritage place is subject to general and specific exemptions if the proposed works will not harm its cultural heritage significance. They are reproduced below:

4.2.1 General exemptions

General exemptions apply to all places and objects included in the VHR. General exemptions have been designed to allow everyday activities, maintenance and changes to your property, which do not harm its cultural heritage significance, to proceed without the need to obtain approvals under the Act.

Specific exemptions may also apply to your registered place or object. If applicable, these are listed below. Specific exemptions are tailored to the conservation and management needs of an individual registered place or object and set out works and activities that are exempt from the requirements of a permit. Specific exemptions prevail if they conflict with general exemptions.

4.2.2 Specific exemptions

The works and activities below are not considered to cause harm to the cultural heritage significance of the Kardinia House subject to the following guidelines and conditions:

Guidelines

- Where there is an inconsistency between permit exemptions specific to the registered place or object ('specific exemptions') established in accordance with either section 49(3) or section 92(3) of the Act and general exemptions established in accordance with section 92(1) of the Act specific exemptions will prevail to the extent of any inconsistency.
- 2. In specific exemptions, words have the same meaning as in the Act, unless otherwise indicated. Where there is an inconsistency between specific exemptions and the Act, the Act will prevail to the extent of any inconsistency.
- 3. Nothing in specific exemptions obviates the responsibility of a proponent to obtain the consent of the owner of the registered place or object, or if the registered place or object is situated on Crown Land the land manager as defined in the Crown Land (Reserves) Act 1978, prior to undertaking works or activities in accordance with specific exemptions.
- 4. If a Cultural Heritage Management Plan in accordance with the Aboriginal Heritage Act 2006 is required for works covered by specific exemptions, specific exemptions will apply only if the Cultural Heritage Management Plan has been approved prior to works or activities commencing. Where there is an inconsistency between specific exemptions and a Cultural Heritage Management Plan for the relevant works and activities, Heritage Victoria must be contacted for advice on the appropriate approval pathway.
- 5. Specific exemptions do not constitute approvals, authorisations or exemptions under any other legislation, Local Government, State Government or Commonwealth Government requirements, including but not limited to the Planning and Environment Act 1987, the Aboriginal Heritage Act 2006, and the Environment Protection and Biodiversity Conservation Act 1999 (Cth). Nothing in this declaration exempts owners or their agents from the responsibility to obtain relevant planning, building or environmental approvals from the responsible authority where applicable.
- 6. Care should be taken when working with heritage buildings and objects, as historic fabric may contain dangerous and poisonous materials (for example lead paint and asbestos). Appropriate personal protective equipment should be worn at all times. If you are unsure, seek advice from a qualified heritage architect, heritage consultant or local council heritage advisor.
- 7. The presence of unsafe materials (for example asbestos, lead paint etc) at a registered place or object does not automatically exempt remedial works or activities in accordance with this category. Approvals under Part 5 of the Act must be obtained to undertake works or activities that are not expressly exempted by the below specific exemptions.
- 8. All works should be informed by a Conservation Management Plan prepared for the place or object. The Executive Director is not bound by any Conservation Management Plan and permits still must be obtained for works suggested in any Conservation Management Plan.

Conditions

xlvi

1. All works or activities permitted under specific exemptions must be planned and carried out in a manner which prevents harm to the registered place or object. Harm includes

moving, removing or damaging any part of the registered place or object that contributes to its cultural heritage significance.


- 2. If during the carrying out of works or activities in accordance with specific exemptions original or previously hidden or inaccessible details of the registered place are revealed relating to its cultural heritage significance, including but not limited to historical archaeological remains, such as features, deposits or artefacts, then works must cease and Heritage Victoria notified as soon as possible.
- 3. If during the carrying out of works or activities in accordance with specific exemptions any Aboriginal cultural heritage is discovered or exposed at any time, all works must cease and the Secretary (as defined in the Aboriginal Heritage Act 2006) must be contacted immediately to ascertain requirements under the Aboriginal Heritage Act 2006.
- 4. If during the carrying out of works or activities in accordance with specific exemptions any munitions or other potentially explosive artefacts are discovered, Victoria Police is to be immediately alerted and the site is to be immediately cleared of all personnel.
- 5. If during the carrying out of works or activities in accordance with specific exemptions any suspected human remains are found the works or activities must cease. The remains must be left in place and protected from harm or damage. Victoria Police and the State Coroner's Office must be notified immediately. If there are reasonable grounds to believe that the remains are Aboriginal, the State Emergency Control Centre must be immediately notified on 1300 888 544, and, as required under s.17(3)(b) of the Aboriginal Heritage Act 2006, all details about the location and nature of the human remains must be provided to the Secretary (as defined in the Aboriginal Heritage Act 2006).

Exempt works and activities

- 6. All internal works to and demolition of the detached post 1960s buildings to the east and west of Kardinia House.
- 7. All internal works to and demolition or removal of the corrugated metal shed located on the southern property boundary.

4.3 Greater Geelong Planning Scheme

The site is covered by HO13 in the local Greater Geelong Planning Scheme:



4.4 Levels of Significance

Fabric of primary significance is as follows:

Fabric of primary significance is that associated with the historical and associative significance of the place with Alexander Thomson.

Fabric of primary significance is also that associated with the history of the place as an important colonial homestead in the region in the nineteenth century up to and including the original fabric of the final 1880s enlargement and additions to the house. These have primary significance due to their demonstration of the evolution of the house from the period of Thomson to the ongoing use of the house as a prestigious residence in the colonial period associated with the associative and historical significance of the house.

Fabric of secondary significance is as follows:

Any original fabric associated with the operation of the house as an early residence in the region up to its conversion from private use, including remnant outbuildings or exterior spaces, landscaping or plantings. This fabric contributes to an understanding of how the house functioned in the period of significance and to its broader setting.


Fabric of no significance can be defined as any fabric associated with the conversion of the house from private use, particularly including all post-war additions and alterations. The removal of such spaces or fabric will have no impact on the cultural heritage significance of the place.

Interior spaces have also been given primary, secondary significance according to their level of integrity or importance to the history of the house. Spaces with low integrity have been generally attributed secondary significance, while spaces with high to medium integrity are of primary significance. Given the level of change throughout the house, most significant spaces are of medium integrity.

4.5 Significance Plan


The following house plan is marked to indicate the areas of primary, secondary and no significance. Note that all original (nineteenth century) external and internal walls are considered to be of primary significance.

KARDINIA HOUSE - EXISTING GROUND FLOOR SIGNIFICANCE PLAN



KARDINIA HOUSE - EXISTING FIRST FLOOR SIGNIFICANCE PLAN

ALL ESTERIAL AND WITERAM, WALLS SHE OF PRIMARY BOWE DATCE APART FROM HED AREAS



INTERNAL ROUND CORNEL CREEN MITCHING, INVOCE - PRIMARY TELLOW INTERNAL BRACES - RECONJUNC ROUNDERSAL - NO BURNESSACE

5 **BIBLIOGRAPHY**

5.1 BOOKS / REPORTS

D. Rowe, About Corayo: A Thematic History of Greater Geelong, City of Greater Geelong, 2021

Statement of Recommendation from the Executive Director, Heritage Victoria Kardinia House, H0337 1 Riverview Terrace, Belmont, 18 March 2024.

Heritage Council Determination, Kardinia House, 6 June 2024.

ARCHIVAL RECORDS AND HERITAGE COLLECTION

Public Record Office of Victoria State Library of Victoria Geelong Heritage Library Victorian Heritage Database

5.2 NEWSPAPERS AND JOURNALS

Geelong Advertiser

T